



BULLETIN: 03D-J-159
LINES: ALL

SERVICE BULLETIN

TO: ALL DISTRIBUTORS AND JOBBERS **DATE: NOVEMBER 21, 2003**

FROM: S. D. CHRISTOPHERSEN, PRODUCT SERVICE & TRAINING

SUBJECT: INFORMATION - ENGINE CRANKCASE FLUSH

DESCRIPTION:

Involved Models: 2003 and Prior GM Cars and Trucks, 2003 HUMMER H2, 2003 and prior Isuzu Light and Medium Duty Trucks with Gasoline Engines

General Motors is aware that some companies are marketing tools and equipment to support engine crankcase flush procedures. **GM does NOT endorse or recommend crankcase flushing for any of its gasoline engines.** Analysis of some of the materials used for crankcase flushing procedures indicates incompatibility with GM engine components and the potential for damage to some engine seals and bearings. **Damage to engine components resulting from crankcase flushing procedures is not covered under the terms of the New Vehicle Warranty.**

ACDelco service bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely.